

(SUBMIT IN TRIPLICATE)

Indian Agency Jicarilla

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Tribal

Allottee

Lease No. Contract 151

RECEIVED
JAN 18 1956
GEOLOGICAL SURVEY
NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Report on surface casing</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ohio Jicarilla #7

January 5, 19 56

Well No. _____ is located 1050 ft. from N line and 990 ft. from E line of sec. 27

Sec. 27 (1/4 Sec. and Sec. No.) 26N (Twp.) 34 (Range) _____ (Meridian)
Jicarilla (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. **To be reported**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12/27/55. Drd to 180', ran 5 jts 158.0h' net of 10 3/4" 32.75# H-40 casing, landed 173.77' KB cemented with 125 sacks, plug down 5 p.m. 12/28/55. good returns.

12/5/55 TD 291h' running 7" casing. Top Picture Cliffs 2908'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Ohio Oil Company

Address P. O. Box 120

Casper, Wyoming

COPY (ORIGINAL SIGNED)
M. J. SOYCE

By _____

Title Division Superintendent of Production