

		■	

**(SUBMIT IN TRIPLICATE)**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency 21001110

Allottee Navilla Tribal

Lease No. Contract 100

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT)

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**July 31st**

19-58

Well No. 2-6 is located 990 ft. from N line and 1650 ft. from E line of sec. 23

Sec. 23  
(1/4 Sec. and Sec. No.)

**Abstract**

20

**K.L.P.N.**

**3. Release PG Ext.**  
(Field)

(Twp.)

(Range)

(Meridian)

## No Affixes

## How to Use Log

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is ~~6366~~ ft.

## DETAILS OF WORK

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

6-11-58 TD 3156' NER. Set 97 joints 3146' of 5-1/2" OD 15.5# J-55 casing at 3155' with 100 sacks cement. Temperature survey showed top of cement at 2480'.  
7-14-58

7-14-58 Pressured up on casing to 1000#. No pressure decrease in one hour.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **EL PASO NATURAL GAS COMPANY**

Address ~~Box~~ **997**

Farmington, New Mexico

By

### Title

**Petroleum Engineer**

