


(SUBMIT IN TRIPLICATE)

Indian Agency Jicarilla TribalContract # 99, Tr. 190UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYAllottee Jicarilla "B"
Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	RECEIVED AUG 30 1957 U. S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXICO
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 28, 1957


Well No. 2 is located 990 ft. from N line and 840 ft. from E line of sec. 14SW 1/4 Section 14
(1/4 Sec. and Sec. No.)26-N
(Twp.)3-W
(Range)N.M.P.M.
(Meridian)Blanco
(Field)Jicarilla
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 7299 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After setting 264' of 5 1/2" Liner on bottom at 6150' with 125 sx cement. Ran Temp. Survey top of cement at 4820'. Cement top of Liner = 3836' with 75 sx cement. Tested top of 5 1/2" Liner with 1500' for 30 minutes. Tested OK. No break.

6150
2364
3786



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MAGNOLIA PETROLEUM COMPANYAddress P.O. BOX 633MIDLAND, TEXASBy L. V. D.
Title Division Superintendent

