

COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBMIT IN TRIPPLICATE TO
DISTRICT OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office N. M.
Lease No. 01381
Unit SW 1/4 Section 24
is designated drilling unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<u>1</u>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<u>1</u>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1-42-201 is located 1600 ft. from SW 1/4 line and 1190 ft. from W 1/2 line of sec. 24
SW 1/4 Section 24 26N 7W 1-11-1
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Blanco-Pictured Cliffs El Arriba County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6141 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

TO 2340'. Ran and cemented 5-1/2" CD Casing at 2340' with 200 sacks. After MC drilled out cement plug and tested casing by boiler for 3 hours. Recovered no water. Casing O.K. Shot with 521 qts. 2340-2370'. Shot exploded O.K. Cleaned out to 2380'. Gas measured 439 MCF after 3 hours. SI waiting on pipe line.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Larry et al Operating Account

Address Room 215

616 East Central Avenue

Albuquerque, New Mexico

By Earl E. McCall

Title Office Manager

