

		16	

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 079287-A

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF WATER SHUT-OFF Hydrofrac	X
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 3, 1960

Intex-South Penn Case USL

Well No. #1-16 is located 1976 ft. from N line and 593 ft. from E line of sec. 16

SE/4 of NE/4

(1/4 Sec. and Sec. No.)

T. 26 N., R. 1 E.

(Twp.)

(Range)

N.M.P.M.

(Meridian)

Puerto Chiquito

(Field)

Rio Arriba

(County or Subdivision)

New Mexico


(State or Territory)

The elevation of the derrick floor above sea level is 7222 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Hydrofrac open hole fractured shale 2076 - 2200' with 930 barrels crude oil. Maximum injection rate 34 barrels per minute. Maximum pressure 1400#. 930 barrels frac oil to recover.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company INTEX OIL COMPANY

Address P.O. Box 1411

Bakersfield, California

PA 4-4956

By R. B. Miller
Title Production Manager

