

aghe

Otis Sub-Surface Pressure Report



15-26-3

Field Jicarilla Well Report No. 40793

Operator Northwest Prod. Corp.

Address 204 North Orchard

Lease E Well No. 11-15 (2in Tubing)
Mesa Verde

Date 11-15-57 Status of Well _____

DEPTH	EXTENSION	PRESSURE	INTERVAL	GRADIENT, # FT.
<u>0</u>	<u>030</u>	<u>30</u>		
<u>1000</u>	<u>231</u>	<u>230</u>	<u>1000</u>	<u>.200</u>
<u>2000</u>	<u>465</u>	<u>463</u>	<u>1000</u>	<u>.235</u>
<u>3000</u>	<u>883</u>	<u>879</u>	<u>1000</u>	<u>.416</u>
<u>4000</u>	<u>1.303</u>	<u>1298</u>	<u>1000</u>	<u>.419</u>
<u>4500</u>	<u>1.513</u>	<u>1507</u>	<u>500</u>	<u>.418</u>
<u>5000</u>	<u>1.730</u>	<u>1723</u>	<u>500</u>	<u>.432</u>
<u>5340</u>	<u>1.872</u>	<u>1865</u>	<u>340</u>	<u>.447</u>

Casing Pressure _____ Tubing Pressure 30 #

Fluid Level _____ Water Level _____

Previous Test Date _____ Previous B.H.P. _____

Change in B.H.P. _____

Previous Bottom Hole Temperature _____

Present Temperature _____

Change in Temperature _____

Instrument Type and No. Amerada # 111440-N Range 0-2000

Date of Latest Calibration 9/19/57

Pressure Run by Strong Interpreted by Same

PRODUCTION
TION

NOV 22 1957

DEPT.
L. G. R. & S. M.

