


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe

Lease No. 03733

Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ 11-19 _____, 1957

Well No. PC 221 is located 890 ft. from N line and 890 ft. from W line of sec. 13

13 (1/4 Sec. and Sec. No.) 26N (Twp.) 7W (Range) BMFM (Meridian)

South Blanco (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6514 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 11-11-57 at 2:00 PM.

Drilled to 105'.

Cemented 8 5/8" 24# J-55 casing at 103' with 80 sacks regular cement. Cement circulated. Plug down 1:00 PM 11-13-57.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Fin G. Lowry

Address P. O. Box 967

Farmington, New Mexico

By Charles E. Veyner

Title Chief Clerk