

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐  
2. NAME OF OPERATOR  
Caulkins Oil Company  
3. ADDRESS OF OPERATOR  
PO Box 780, Farmington, New Mexico  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 890' F/N 890' F/W  
AT TOP PROD. INTERVAL: Same  
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| REQUEST FOR APPROVAL TO:                           | SUBSEQUENT REPORT OF:    |
|--|--------------------------|
| TEST WATER SHUT-OFF <input type="checkbox"/>       | <input type="checkbox"/> |
| FRACTURE TREAT <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/>          | <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/>               | <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>      | <input type="checkbox"/> |
| MULTIPLE COMPLETE <input type="checkbox"/>         | <input type="checkbox"/> |
| CHANGE ZONES <input type="checkbox"/>              | <input type="checkbox"/> |
| ABANDON* <input type="checkbox"/>                  | <input type="checkbox"/> |
| (other) <input type="checkbox"/>                   | <input type="checkbox"/> |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

It is proposed to clean out to 2785' then determine that all perforations are open.

W Well will be fractured w/50,000# sand.

Est. starting date June 15, 1979.

A small pit on existing location will be required to contain frac water while cleaning up.

All disturbed area will be cleaned up and reseeded.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

Set @ \_\_\_\_\_

18. I hereby certify that the foregoing is true and correct

SIGNED Charles Vergun TITLE Superintendent DATE March 20, 1979

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

5. LEASE  
NM-03733  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
Breech  
9. WELL NO.  
221  
10. FIELD OR WILDCAT NAME  
South Blanco PC  
11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA  
Sec. 13 26N-8W  
12. COUNTY OR PARISH  
Rio Arriba  
13. STATE  
New Mexico  
14. API NO.  
15. ELEVATIONS (SHOW DE KDB AND WD)  
6514' DE

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED  
MAR 26 1979

U. S. GEOLOGICAL SURVEY  
DANANGO, COLO.