

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 300390651202-S1
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-291-25
7. Lease Name or Unit Agreement Name State "B" Comm
8. Well No. 233
9. Pool name or Wildcat Basin Dakota
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6697 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Caulkins Oil Company
3. Address of Operator P.O. Box 340, Bloomfield, New Mexico 87413

4. Well Location Unit Letter D : 1145 Feet From The North Line and 980 Feet From The West Line Section 16 Township 26 North Range 6 West NMPM Rio Arriba County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Repaired Packer Leak <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-15-92 Pulled tubing and Packer, found hole in tubing above packer.
Replaced bad joints, re-ran tubing to 7116', set packer at 3278'.
No new surface disturbed.

RECEIVED
OCT 26 1992
OIL CON. DIV
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert L. Verquer TITLE Assistant Superintendent DATE 10/22/92
TYPE OR PRINT NAME Robert L. Verquer TELEPHONE NO. 632-1544

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERINTENDENT DATE 10/22/92

CONDITIONS OF APPROVAL, IF ANY: