UNITED STATES

UNITED STATES	5. LEASE កុន្តីខ្លួញ ខ្លួញ និធីក
DEPARTMENT OF THE INTERIOR	NM-03554
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GLOLOGIONE JONALI	는 소수의 - 6 - 주변 <mark>부</mark>
SUNDRY NOTICES AND REPORTS ON WELL	7. UNIT AGREEMENT NAME
Open use this form for proposals to drill or to deepen or plug back to a di	ifferent and a second a second and a second
(Do not use this form for proposals to drill or to deepen or plug back to a di reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME 9 0 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9
1. oil gas 🙀	Breech C 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
well well tother	9. WELL NO. 2 3 3 4 5 4 5 4 5 4 5 6 6 6 6 6 6 6 6 6 6 6 6
2. NAME OF OPERATOR	
Caulkins Oil Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Dastii Banoca
P.O. Box 780 Farmington, New Mexico	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See spa	Section 14 226 North 26 West
below.) AT SURFACE: 990' F/S & 990' F/W	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same	Rio Arriba New Mexico
AT TOTAL DEPTH: Same	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NO	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6616 GL. క్రైవేరు
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT C	
TEST WATER SHUT-OFF	<u> </u>
FRACTURE TREAT	현실 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES	eliasyt maga s maga s maga s maga hugan maga an maga maga an maga an
ABANDON* [] [] (other) Repair Tubing	Beroilausta Clemano Be Clemano Be Clemano Be Clemano Beriala nol poibal de fectione to set bus mano Sett
	<u> </u>
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clear including estimated date of starting any proposed work. If w	rly state all pertinent details, and give pertinent dates,
measured and true vertical depths for all markers and zones p	pertinent to this work.)* 10 20 20 30 4 4 5 5
	talled a 10
6-14-80 Found 2 3/8" tubing had p	parted.
Fished out all 2 3/8" tu	bing, Then ran
new 2 3/8" OD EUE tubing	8rd thread J-55 10 10 10 10 10 10 10 10 10 10 10 10 10
	TO SEE SEE SEE SEE SEE
to 7441'.	AND THE PROPERTY OF THE PARTY O
	The state of the s
	Heliza real to the total control of the total contr
	전기의 전 등 전 등 전 등 전 등 등 등 등 등 등 등 등 등 등 등 등
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	HE H
	그는 그는 그 사용한 10 개석이다.
SIGNED CLASSIFIE Superi	ntendent DATE 9-29-80
(This space for Federal or	State office use)
- (this space for redefail of	
ALL HOVED D.	DATE
CONDITIONS OF APPROVAL, IF ANY:	
	FREE PACEUTED FOR RECO

*See Instructions on Reverse Side

00T 8 1980

