
DEC 2 9 1997

Meter Number:71820 ocation Name:RINCON UNIT #95 Location:TN-26 RG-07 SC-12 UL-I 2 - Federal **NMOCD Zone:OUTSIDE**

Hazard Ranking Score:00



RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

10⁻⁹ to 10⁻¹³ cm/sec Sandstone 10⁻¹² to 10⁻¹⁶ cm/sec Shale 10⁻¹² to 10⁻¹⁵ cm/sec Clav

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.



FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: 7/820 Location: Reven Unit 15 Operator #: 9/65 Operator Name: Laure P/L District: Beauco Coordinates: Letter: I Section 2 Township: 26 Range: 2 Or Latitude Longitude Pil Type. Dehydrator Location Drip: X Line Drip: Other: Site Assessment Date: 12-8-94 Area: 3 Run: 72				
	NMOCD Zone: Land Type: BLM 🗵 (1)				
ĺ	(From NMICCD State \square (2) Maps) Inside \square (1) Fee \square (3)				
	Outside 💢 (2) Indian				
	Depth to Groundwater Less Than 50 Feet (20 points) (1)				
	Less Than 50 Feet (20 points) \square (1) 50 Ft to 99 Ft (10 points) \square (2)				
	Greater Than 100 Ft (0 points) 🗵 (3)				
ASSESSMENT	Wellhead Protection Area : Is it less than 1000 ft from wells, springs, or other sources of				
	fresh water extraction? , or ; Is it less than 200 ft from a private				
	domestic water source? (1) YES (20 points) 🔀 (2) NO (0 points)				
	Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) (1)				
SITE	200 Ft to 1000 Ft (10 points) (2)				
S	Greater Than 1000 Ft (0 points) 🗷 (3) Name of Surface Water Body				
	(Surface Water Body : Perennial Rivers, Major Wash, Streams, Creeks,				
	Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream (1) < 100' (Navajo Pits Only)				
	Distance to Nearest Epnemeral Stream \square (1) < 100 (Navajo Pits Only) \square (2) > 100'				
	TOTAL HAZARD RANKING SCORE: POINTS				
KS	Remarks: TOPO + REDUNE - OUTSIDE				
EMARKS	DUSH-IN				
田	PUSH-IN				

ORIGINAL PIT LOCATION	ORIGINAL PIT LOCATION Original Pit: a) Degrees from North <u>2/2</u> Footage from Wellhead <u>/45</u> b) Length: <u>/5′</u> Width: <u>/5′</u> Depth: <u>7′</u>
	145-1- 2120
0	195-7 15'
	kemarks :
REMARKS	
	Completed By:

Date

Signature

FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 71820 Location: RiNcoH UNIT 95 Coordinates: Letter: Section 12 Township: 26 Range: 7 Or Latitude Longitude Longitude Date Started: 1-10-95 Run: 03 72
FIELD OBSERVATIONS	Sample Number(s): # 378 Sample Depth: Feet Final PID Reading PID Reading Depth Feet Yes No Groundwater Encountered
CLOSURE	Remediation Method: Excavation
	Soil Disposition: Envirotech Other Facility Name: Pit Closed By: 3.57
REMARKS	Remarks: Some Line markers. dug A Test hole. To 12 SAMPLE CLOSER PIT
	Signature of Specialist: Kells Padilla

(SP3191) 03/16/94



FIELD SERVICES LABORATORY ANALYTICAL REPORT

PIT CLOSURE PROJECT - Soil Samples Outside the GWV Zone

SAMPLE IDENTIFICATION

Field ID	Lab ID		
KP378	946565		
71820	N/A		
1-10-95	140 0		
N/A			
1-12-45	1 - 12 -95		
NIA	N/A		
VG	light Gray clay		
	KP378 71820 1-10-95 1-12-45 NJA		

PARAMETER	RESULT UNITS		QUALIFIERS			
			DF	Q	M(g)	V(ml)
TPH (418.1)	158	MG/KG			1.99	28
HEADSPACE PID	147	РРМ				
PERCENT SOLIDS	88.8	%				1996 1997 1998

147	1 1 141		 	
88.8	%			14.4 14.7
	TPH is by EPA Metho	d 418.1		
1		Date:	2-22-45	
	88.8	88.8 %	88.8 % TPH is by EPA Method 418.1	88.8 %

****************** Test N_ chod for Oil and Grease and Petroleum Hydrocarbons in Water and Soil

Perkin-Elmer Model 1600 FT-IR Analysis Report ********************************

95/01/12 11:15

55.55

Sample identification 246565

Initial mass of sample, g 1.790

Valume of sample siter extraction, ml

Patricleum hydrocartors, ppm 157-662 Net Absorbarce if Avdrocarbons (2730 cm-1) 1 927

it formaleum y modernouns specthum

113

5.70595

*

ILLEGIBLE

1990