


STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office S. F.
Lease No. 075035-A
Unit S4/4, Sect. 10



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 30, 19 51

Well No. 5-15-181 is located 1510 ft. from NE line and 135 ft. from EW line of sec. 10

S4/4, Section 10 26N 6W 1951
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Bio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6563 ft. GL

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 11-12-51.
Cemented 8 5/8" casing at 575', w/175 sacks cement.
ramped plug 544'. Cement circulated.
Tested casing w/600# for one hour. No decrease.
Cemented 5 1/2" casing at 2975' w/200 sacks.
ramped plug to 2910'. Tested w/600# for 3 hours. No decrease.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company Lowry et al Operating Account

Address Room 213

616 East Central Avenue

Albuquerque, New Mexico

By [Signature]
E. V. Richardson
Title Business Manager



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL		
NOTICE OF INTENTION TO PULL OR ALTER CASING		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		
NOTICE OF INTENTION TO CHANGE PLANS		
NOTICE OF INTENTION TO DRILL		
SUPPLEMENTARY WELL HISTORY		
SUBSEQUENT REPORT OF ABANDONMENT		
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
SUBSEQUENT REPORT OF ALTERING CASING		
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
SUBSEQUENT REPORT OF WATER SHUT-OFF		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE OR OTHER DATA)

Well No. _____ is located _____ ft. from _____ line and _____ ft. from _____ line of sec. _____

_____ (Field) _____ (County or Subdivision) _____ (State or Territory)
_____ (Twp.) _____ (Range) _____ (Meridian)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casing; indicate mudding jobs, cementing points, and all other important proposed work)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _____

Address _____

By _____

Title _____