


COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBMIT IN TRIPLICATE TO
DISTRICT OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 27 079035-4

Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. T-21-10-102 is located 1740 ft. from XXX line and 1800 ft. from XXX line of sec. 10
NE 24/4 Sec. 10 26N 6W N.M.P.M.
Pattagonia (Field) Rio Arriba County (County or Subdivision) New Mexico (State or Territory)
(Twp.) (Range) (Meridian)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)
TD 6701'. Ran and cemented 7-5/8" ID Casing at 6700' with 175 sacks. Ran Schlumberger Survey. After W.T., drilled cement plug and pressured up to 600# for 1 hour. Casing O.K. Drilled to TD 6761'. Ran Tubing. Now muddling.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Lease of and Operating Account

Company _____
Address 615 E. Central Avenue
Albuquerque, New Mexico

By L. E. Richardson
Business Manager
Title _____