



**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

Land Office \_\_\_\_\_  
Lease No. 770354  
Unit \_\_\_\_\_

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

\_\_\_\_\_ 12 \_\_\_\_\_, 19 53

Well No. 4-22-177 is located 1200 ft. from S line and 600 ft. from W line of sec. 9

14 Sec. - 9 (1/4 Sec. and Sec. No.)      34 (Twp.)      6 (Range)      111 (Meridian)

Utterson (Field)      Alb. Co. (County or Subdivision)      Cal. Mexico (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

*drilled to 27 6.45'. ran 2" tubing to 112'. cemented well in.  
Test 160.0 bbls oil in 22 hours. test in.*

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Lovely et al Operating Account

Address 614 N. Central

Albuquerque

N. Mex.

By *[Signature]*

G. J. Harrison  
Title Assistant General Manager

