



WSS - 6
File - 1

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____
_____ **Stearns** _____
Allottee **Stearns #110** _____
Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 12, 1976, 19__

Well No. W 7-6 is located 1190 ft. from N line and 1190 ft. from E line of sec. 8
NE/4 NE/4 8 Sec 4 N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco Monarche Gas Pool Rio Arriba New Mexico
Negativo (SW) Gas Pool Area (County or Subdivision) (State or Territory)

The elevation of the ~~surface~~ ground above sea level is 7143.0 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 2:30 p.m. 6-24-76. Drilled to 133' and set 119.00' of 2-1/2" OD 2-40 30.30# 8-20 casing with guide shoe set at 134.35' and cemented with 100 cu regular. FOS 10:15 p.m. 6-24-76. After 24 hours WBS, casing tested OK. Drilling ahead.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company STEARNS PRODUCTION CORPORATION
Address 300 Stone Building
Albuquerque, New Mexico
By Ray Phillips, Jr.
Title Asst. Mgr., Prod. Operations