5. Lease UNITED STATES NMSF-079035-A DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 6. If Indian, Allottee or Tribe Name SUNDRY NOTICES AND REPORTS ON WELLS 7. Unit Agreement Name (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT--" for such proposals) 8. Well Name and No. 1. Oil Well [] Gas Well [] Other [] **GAS WELL BREECH "A" 132** 2. Name of Operator: 9. API Well No. Caulkins Oil Company 30-039-06635-00S1 3. Address of Operator: 10. Field and Pool, Exploratory Area (505) 632-1544 P.O. Box 340, Bloomfield, NM 87413 **BASIN DAKOTA** 4. Location of Well (Footage, Sec., Twp., Rge.) 11. Country or Parish, State 660' F/N 760' F/E SEC. 9-26N-6W Rio Arriba Co., New Mexico 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION [] Notice of Intent [X] Abandonment [] Change of Plans []Recompletion [] New Construction [X] Subsequent Report [] Plugging Back Non-Routine Fracturing [] Casing Repair [] Water Shut-Off [] Final Abandonment Notice [] Altering Casing [] Conversion to Injection [] Other 1 Dispose Water 17. Describe Proposed or Completed Operations: 3-6-00 Rigged up. T.O.H. with 2 3/8" tubing and 4 1/2" packer. NOTE: When packer released, casing went on hard vacuum indicating a hole in 7" casing. Also, outside of tubing had marks and drilling mud from approximately 2300'. Decision to plug and abandon well was made at this time. Verbal approval was obtained from both federal and state agencies to proceed with plug and abandonment. Plugging procedures as follows: 3-7-00 T.I.H. with 2 3/8" tubing. Spotted first plug, 7275 '- 6723', with 8.78 bbls (35 sacks, 48 cu. ft.) Type III neat cement. Pulled 20 stands. Shut down 3 hours. T.I.H. tagged cement at 6719'. Spotted second plug, 6464 '- 6308', with 8.78 bbls (35 sacks, 48 cu. ft.) Type III neat cement. (continued on page 2) NOTE: The format is issued in lieu of U.S. BLM Form 3160-5 18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT SIGNED: TITLE: Superintendent DATE: March 23, 2000 ROBERT L. VEROUER APPROVED BY: DATE: ACULTED FOR RECORD TITLE: CONDITIONS OF APPROVAL, IF ANY

Caulkins Oil Company BLM Sundry Notice Breech "A" 132 March 23, 2000 Page 2

3-7-00

Spotted third plug, 5491 '- 5335', with 5.74 bbls (23 sacks, 31.5 cu. ft.) Type III neat cement.

Pulled 20 stands.

Shut down overnight.

3-8-00

Tagged top of cement at 5323'.

T.O.H. with tubing.

Perforated 7" casing at 4682'.

T.I.H. with cement retainer to 4650'.

Spotted fourth plug, inside and outside of 7" casing, 4643' – 4486', with 11 bbls (44 sacks, 60.2 cu. ft.) Type III neat cement.

T.O.H.

Perforated at 3878'.

T.I.H. with cement retainer to 3830'.

Spotted fifth plug, inside and outside of 7" casing, 3854' – 3697', with 11 bbls (44 sacks, 60.2 cu. ft.) Type III neat cement.

T.O.H.

Shut down overnight.

3-9-00

Perforated at 2988'.

T.I.H. with cement retainer to 2930'.

Spotted sixth plug, inside and outside of 7" casing, 2939' – 2789', with 11 bbls (44 sacks, 60.2 cu. ft.) Type III neat cement.

T.O.H.

Perforated at 2709'.

T.I.H. with cement retainer to 2660'.

Spotted seventh plug, inside and outside of 7" casing, 2709' – 2178', with 34.5 bbls (138 sacks, 189 cu. ft.) Type III neat cement.

During above job, circulation was established through Bradenhead.

T.O.H. laying down remainder of 2 3/8" tubing.

Perforated 7" casing at 948'.

Circulated eighth plug, 948' to surface, with 73 bbls (292 sacks, 400 cu. ft.) Type III neat cement.

Permanent marker was welded to 7" casing to mark wellbore.

BLM representative, Mr. Ron Snow, was on location during all plugging operations.

3-10-00

All surface equipment has been removed. Location will be contoured and re-seeded to meet federal and state requirements.