



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **079161**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Change of Well Operator	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Candado **February 11,** 19**63**
Well No. **4** is located **450** ft. from **XX** line and **450** ft. from **EX** line of sec. **3**
SW/4, SW/4, Sec. 3 **26 N** **7 W** **N.M.P.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
So. Blanco-PC **Rio Arriba** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6139**ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The operator of the above-mentioned well is Bolin Oil Company, effective September 1, 1962 at 7:00 A.M.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Bolin Oil Company**
Address **1120 Oil & Gas Building**
Wichita Falls, Texas

By **R. T. DeLoach**
Title **Partner**