



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **03551**
Unit **Breech "B"**

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|--|--|-------------------------------------|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 28, 1960

Well No. **T-102** is located **660** ft. from **S** line and **1980** ft. from **W** line of sec. **5**
SE 1/4 SW 1/4 **5** **26N** **6W** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Platte Tociro **Rio Arriba** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6526** ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded at 6:30 A.M., 1-21-60.

1-22-60 - Drilled to TD 461'. Ran 10 3/4" 32.75# H-40 Casing to 461' and cemented w/300 sacks cement, 2% calcium. Plug down at 9:00 A.M., 1-22-60.

I understand that this plan of work must receive approval in writing by the Geological Survey before any work may be commenced.

Company **Caulkins Oil Company**

Address **Box 967**

Farmington, New Mexico

By *Charles J. [Signature]*

Title **Production Foreman**

