



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 03551  
Unit \_\_\_\_\_  
Branch ALB

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Supplement report of fracturing

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 9, 1958

Well No. 27 is located 1725 ft. from S line and 1510 ft. from W line of sec. 4  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
South Lincoln 10 Arriba New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5443 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-10-58 - Fractured 210 ft. to 250 ft. sand oil, 150 gallons water.  
Fracturing procedure 1800-  
Fracturing procedure 1800 to 1850  
Final pressure 170 when pumps were started.  
Fracture inject: 1800 to 1850.

Water level before treatment 180 ft. per day.  
Availability water about 500 ft. per day.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Wulkins Oil Co., Inc.

Address 2000 1st St. N.E.

Albuquerque, N.M.

By [Signature]

Title Field Representative