

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

WELL NO. 4-15  
FIELD NO. 12-31-76

SP 079162  
B. INDIAN, ALLIANCE OF TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

|   |  |   |  |
|---|--|---|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER   |  | 7. UNIT AGREEMENT NAME  |  |
| 2. NAME OF OPERATOR<br>DEPCO, Inc.  |  | 8. FARM OR LEASE NAME<br>MKL  |  |
| 3. ADDRESS OF OPERATOR<br>1025 Petroleum Club Building, Denver, CO 80202  |  | 9. WELL NO.<br>4-15   |  |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.<br>See also space 17 below.)<br>At surface<br>990' FNL, 990' FEL<br>Sec. 5, T26N, R7W |  | 10. FIELD AND POOL, OR WILDCAT<br>Blanco South, P.C.                  |  |
| 14. PERMIT NO.  |  | 11. SEC., T., R., M., OR BLC. AND SURVEY OR AREA<br>Sec. 5, T26N, R7W |  |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br>GR 6637'  |  | 12. COUNTY OR PARISH<br>Rio Arriba                                    |  |
|   |  | 13. STATE<br>N. M.  |  |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO:                      |   | SUBSEQUENT REPORT OF:                          |  |
|--|---|--|--|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> | WATER SHUT-OFF <input type="checkbox"/>        | REPAIRING WELL <input type="checkbox"/>  |
| FRACTURE TREAT <input type="checkbox"/>      | MULTIPLE COMPLETE <input type="checkbox"/>    | FRACTURE TREATMENT <input type="checkbox"/>    | ALTERING CASING <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/>    | ABANDON* <input type="checkbox"/>             | SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT* <input type="checkbox"/>    |
| REPAIR WELL <input type="checkbox"/>         | CHANGE PLANS <input type="checkbox"/>         | (Other) <input type="checkbox"/>               |  |


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

MKL 4-15 has not had any gas sales since May, 1971 when the well died. The well had been producing approximately 1000 MCF/Mo.

In July, 1971, the well was cleaned out to bottom and swabbed in an attempt to restore production. This effort was not successful.

DEPCO, Inc., requests approval to place the MKL No. 4-15 well on a temporary abandoned status pending evaluation of results of a recently drilled well, the Hancock No. 8R, Sec. 12, T27N, R12W, San Juan County, New Mexico.



18. I hereby certify that the foregoing is true and correct

SIGNED John S. Skyles TITLE Dist. Prod. Supt. DATE October 28, 1975

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: