## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

UNITED STATES  DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	5. LEASE NM 03554 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME  8. FARM OR LEASE NAME
1. oil gas K other	Breech C 9. WELL NO. 323E
2. NAME OF OPERATOR  Caulkins Oil Company  3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Otero Chacra Blanco Mesa Verde, Basin Dakota
P.O. Box 780 Farmington, New Mexico  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.) AT SURFACE: 1120' F/S & 1020' F/E AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	Section 14 26N 6W  12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico  14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	

3. ADDRESS OF OPERATOR P.O. Box 780 Farmington, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1120' F/S & 1020' F/E AT SURFACE: AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6678**1** REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE (NOTE: Report results of multiple completion or zo REPAIR WELL change on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON\* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* Spud at 8:00 **♣**M 8-02-81. Drilled 13 3/4" hole to 2921. Ran 9 5/8" 32.30# H-40 casing to 292' & cemented with 250 sacks Class B cement, 2% CaCl. Cement circulated to surface. Plug down 7:00 AM 8-03-81. Cement set 24 hours, then tested 9 5/8" casing with 600# for 30 8-04-81 minutes. No decrease in pressure. Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_ Ft. 18. I hereby certify that the foregoing is true and correct Multir Superintendent DATE (This space for Federal or State office use) DATE APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

L1G 1 7 198

\*See Instructions on Reverse Side