

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

Sundry Notices and Reports on Wells

1. Type of Well
GAS

5. Lease Number
SF-078878

6. If Indian, All.or
Tribe Name

2. Name of Operator
Meridian Oil Inc.

7. Unit Agreement Name
Canyon Largo Unit

3. Address & Phone No. of Operator
Box 4289, Farmington, NM 87499 (505) 326-9700

8. Well Name & Number
Canyon Largo Unit #173

9. API Well No.

4. Location of Well, Footage, Sec, T, R, M.
990'S, 800'E Sec. 28, T-25-N, R-7-W, NMPM

10. Field and Pool
Ballard Pictured Cliffs

11. County and State
Rio Arriba County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

Type of Action

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☒ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut Off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

It is proposed to repair a casing leak in the subject well per the following procedure (see attached wellbore schematic):

TOOH w/tbg & pkr. Set a RBP above the Pictured Cliffs @ 2000'. Isolate and squeeze the leak in the 2 7/8" casing w/Class "B" neat cmt. Drill out squeeze and pressure test. Pull RBP. TIH w/tbg and pkr. Return well to production.

RECEIVED

OCT 9 1991

OIL CON. DIV.
DIST. 2

14. I hereby certify that the foregoing is true and correct.
Signed [Signature] (LS) Title Regulatory Affairs Date 9-23-91

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITION OF APPROVAL, IF ANY:

OCT 08 1991
DATE

FARMINGTON, NM

Canyon Largo Unit #173
Unit P of Sect 28-T25N-R7W
Rio Arriba County, New Mexico

Wellbore Schematic

CURRENT

PROPOSED

