l'orm 9-331 (May 1983)	UNITED STATES DEPARTMENT OF THE IN- GEOLOGICAL SURVE		Form approved. Budget Bureau No. 42-R1424.  5. LEASE DESIGNATION AND SERIAL NO. 11.1 03553
(Do not use this	DRY NOTICES AND REPOR form for proposals to drill or to deepen or Use "APPLICATION FOR PERMIT—" for	6. IF INDIAN, ALLOTTSE ON TRIBE NAME  7. UNIT AGREEMENT NAME	
OIL GAS WELL WELL	OTHER		
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Caulkins Oil Company			Breech D
3. ADDRESS OF OPERATOR			383
Post Office Box 780, Farmington, New Mexico 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, OR WILDCAT-
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  See also space 17 below.)  At surface			South Blanco - Otero Chacr
790 from South and 1650 from East of Sec. 21 25 North 6 West			11. SEC., T., B., M., OR BLK. AND SURVEY OR ARMA
170 1101 20001 4114 1107			Sec. 21 26 North 6 West
14. PERMIT NO.	15. ELEVATIONS (Show who	ether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	6707 DF		Rio Arriba New Mexico
16.	Check Appropriate Box To India	ate Nature of Notice, Report, or C	Other Data
1	NOTICE OF INTENTION TO:	SUBSEQ	UENT REPORT OF:
TEST WATER SHUT-O	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	A Wall
(Other)		(Note: Report results Completion or Recomp	s of multiple completion on Well letion Report and Log form.)
17. DESCRIBE PROPOSED OF	R COMPLETED OPERATIONS (Clearly state all p well is directionally drilled, give subsurfa	ertinent details, and give pertinent dates ce locations and measured and true vertic	, including estimated date of starting any cal depths for all markers and zones perti-
nent to this work.)		• •	
TD 4000 . R	an Casing as follows:		
		ar and an area of the second of the	GD0 G
0	53.00 2 jts.	5 1/2" 15.5% J-55 Sm	LS. SIGO
53.00	3893.39 <b>123</b> 4000.00 4	5 1/2" 15.5% J-55 Sml 4 1/2" 12.6% J-55 Sml 4 1/2" 10.5% J-55 Sml	LS. SIEU
3 <sup>8</sup> 93•39	1,000,00	4 1/2" 10.5# J-55 Sm	ra• prec
Cemented thr	ru shoe with 215 sacks, lo	dense cement followed by	195 sacks neat.
Plug down 5:	00 PM 8-29-74		
Tempe rature	survey run 8-30-74 showed	top of cement at 2000.	
100020200		<b>1</b>	
	per concept of many		
		1000	
	in the second of		목원하는걸 원동 결약회회
	5 T G	· co	
		Total	
		3/	
		A second second	
18. I hereby certify that	the foregoing latrue and correct		
SIGNED	Survey THE	E Superintendent	PATE 9-8-74

TITLE \_

DATE \_\_\_

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_\_\_ CONDITIONS OF APPROVAL, IF ANY: