| Forn. 9-331 (May 1963) DEPAR | UNITED STATES SUBMIT IN TRIPLICATE (Other Instructions on verse side) GEOLOGICAL SURVEY | Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. NM 03.733 |
|---|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) | | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| OIL GAS WELL A OTHER 2. NAME OF OPERATOR | | 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME |
| Caulkins Oil Company 3. ADDRESS OF OPERATOR | | Breech |
| P.O. Box 780 Fa 4. LOCATION OF WELL (Report location See also space 17 below.) At surface | rmington. New Mexico 87401 a clearly and in accordance with any State requirements.* | 258 South Blanco wildcat Otero Chacra 11. Sec., T., E., M., OR BLE. AND |
| 1450 from the | North and 1850 from the West | Sec. 18 26N 6W |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, RT, GR, etc.) | Rio Arriba New Mexic |
| 16. Check A | Appropriate Box To Indicate Nature of Notice, Report, o | |
| NOTICE OF INT | | SEQUENT REPORT OF: |
| TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) | Completion or Reco | REPAIRING WELL ALTERING CASING ABANDONMENT* ults of multiple completion on Well mpletion Report and Log form.) |
| 17. DESCRIBE PROPOSED OR COMPLETED 0 proposed work. If well is direc nent to this work.) * | PERATIONS (Clearly state all pertinent details, and give pertinent da tionally drilled, give subsurface locations and measured and true ver | Ann. () |
| Ran 4: 347 sa | ed to TD 3480. Ran Ind and Densi 12. 12.6# J-55 tubing to 3480. and acks 65-35-12 gel cement followed down 2:30 AM 7-6-76. Cement circu | d cemented with by 177 sacks neat. |
| 18. I hereby certify that the foregoing | | 7 7 7 |
| (This space for Federal or State of | Ciliqui TITLE Superintendent | DATE 7-7-76 |
| APPROVED BYCONDITIONS OF APPROVAL, IF | TITLE | DATE DEGELVE |

JUL 14 1976

19 11 N S S