

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM 03551

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | |
|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> | 7. UNIT AGREEMENT NAME |
| 2. NAME OF OPERATOR Caulkins Oil Company | 8. FARM OR LEASE NAME Breech # E |
| 3. ADDRESS OF OPERATOR Post Office Box 780, Farmington, New Mexico | 9. WELL NO. 558 |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1180 from the North and 820 from the East | 10. FIELD AND POOL, OR WILDCAT South Blanco PC |
| 14. PERMIT NO. | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3 26N 6W |
| 15. ELEVATIONS (Show whether DF, RT, CR, etc.) 6560 Gr. | 12. COUNTY OR PARISH 13. STATE Rio Arriba New Mex. |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spud at 6:00 PM 4-24-77.

Drilled 12 1/4" hole to 102'.

Cemented 3 5/8" 24# J-55 casing at 102' with 100 sacks class B cement containing 2% CaCl. Plug down 10:00 PM 4-24-77. Cement did circulate to surface.

Surface pipe tested with 500# 4-25-77. No decrease in pressure.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Superintendent

DATE

4-25-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side