5. LEASE

Contract #105

UNITED STATES DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a difference of the support of t	7. UNIT AGREEMENT NAME
Do not use this form for proposals to trill or to deepen of plug back to a times eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME Jenny
1. oil gas Well X other	9. WELL NO.
2. NAME OF OPERATOR Consolidated Oil & Gas, Inc.	#1-A 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Mesaverde - Gallup
1860 Lincoln St., Denver, Colo 80295	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1 below.) 	Sec. 13, T26N, R4W, NMPM
AT SURFACE: 990' FSL & 790' FEL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE New Mexico
AT TOTAL DEPTH: 81001	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTIC REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7085' Gr.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
PULL OR ALTER CASING U U MULTIPLE COMPLETE	change on Form 9-330.)
CHANGE ZONES	
ABANDON*	*
4-20-78 MOL - Rig Up. Spud 2:45 p.m.	10 0 M 10 5 M 11 10 0 ms 0
and set (d 297' K.B. Omt'd w/300	x Cl "B" w/2% cc 2#/Cellfalke/sx. 30 cmt. dropped back. WOC 5 hrs.
4-22-78 Cemented 10 3/4" annulus via 1" t Cmt. circ. to surface and did not csg. to 700 psi - 0.K.	cubing w/50 sx Cl "B" w/3% Cacl. fall back. WOC 6 hrs. Tested
Subsurface Safety Valve: Manu. and Type	Set @ Ft
18. Thereby certify that the foregoing is true and correct	5-2-78
SIGNED TITLE TOUS SUP	DATE
(This space for Federal or State	DATE
CONDITIONS OF APPROVAL, IF ANY: *See Instructions on Revi	MAY SHIP ME TO THE TOTAL PROPERTY OF THE PARTY OF THE PAR
See Instructions on New	DIST. 3 7 1 3 1918
State	DURANGO, COLO.