| Form | 9-331 |
|------|-------|
| (May | 1963  |

## **UNITED STATES** DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

| 3.736 | 00000 |
|-------|-------|
| MM    | 03381 |

| SUNDRY NOTICES AND REPORTS ON WE (Do not use this form for proposals to drill or to deepen or plug back to a (Use "APPLICATION FOR PERMIT—" for such proposals.) | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME lifterent reservoir. |
|--|---|
| OIL GAS WELL WELL OTHER  | 7. UNIT AGREEMENT NAME                                    |
| 2. NAME OF OPERATOR  Caulkins Oil Company  | 8. FARM OR LEASE NAME Breech B                            |
| 3. ADDRESS OF OPERATOR P.O. Box 780 Farmington, New Mexico   | 9. WELL NO.   |
| <ol> <li>LOCATION OF WELL (Report location clearly and in accordance with any State required See also space 17 below.)</li> <li>At surface</li> </ol>            | irements.• 10. Statut P Blancoc PC                        |

1130 from the South and 860 from the East

26N 6W 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH | 13. STATE 6407 Gr Rio Arriba N Mex.

Otero-Chacra 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| SUBSEQUENT REPORT OF:   |  |  |  |  |  |
|---|--|--|--|--|--|
| TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  (Other) | WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other)  (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) |  |  |  |  |
| Completion of Recompletion Report and Log 10rm.)                            |  |  |  |  |  |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spud at 12:00 Midnight 6-7-78

Drilled 12 1/4" hole to 105'

Cemented 8 5/8" 24# K-55 new casing at 105 with 85 sacks of 2% CaCl

Plug down 3:30 AM 6-7-78

Cement circulated to surface

Tested surface casing 6-8-78 with 500# for 30 minutes. No decrease in pressure

| 8. I hereby certify that the foregoing is true and correct SIGNED | TITLE | December 1    | ( 10 74      |
|---|-------|---------------|--------------|
|   | TITLE | Prod. Foreman | DATE 6-10-78 |
| (This space for Federal or State office use)                      |       |               |              |
| APPROVED BY   | TITLE |               | DATE         |
| CONDITIONS OF APPROVAL, IF ANY:                                   |       |               | JUN 1 6 1978 |