

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other _____
2. NAME OF OPERATOR
AMOCO PRODUCTION COMPANY
3. ADDRESS OF OPERATOR
501 Airport Drive Farmington, NM 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1145' FSL x 950' FEL, Section 3,
AT SURFACE: T-26-N, R-4-W
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) Completion-Perf & Frac		


5. LEASE
Jicarilla Apache 102
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Jicarilla Apache 102
9. WELL NO.
28
10. FIELD OR WILDCAT NAME
B. S. Mesa Gallup
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SE/4 SE/4 Section 3,
T-26-N, R-4-W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
NM
14. API NO.
30-039-21554
15. ELEVATIONS (SHOW DF, KDB, AND WD)
6890' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Completion operations commenced 3/19/78. Tripped in with tubing and bit; cleaned out to 7419' PBD. Tested casing to 3000 psi for 15 minutes; held OK. Perforated 6999-7367'. Fraced with 189,000 lbs. sand and 94,500 gallons frac fluid. Tripped in with tubing and bit; cleaned out frac sand and fluid to 7419'. Production tubing landed at 7361'.

Completion rig released 3/23/78.



Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE Adm. Supervisor DATE 4/18/78

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

APR 19 1978

U.S. GEOLOGICAL SURVEY
FARMINGTON, N.M.