5. LEASE

Contract No. 153

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas ra	Jicarilla "J"
1. Oil gas well other	9. WELL NO.
2. NAME OF OPERATOR	16
SUPRON ENERGY CORPORATION	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	South Blanco Pictured Cliffs
P.O. Box 808, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 26, Twp. 26N, Rge-5
below.)	N.M.P.M.
AT SURFACE: 1190 ft./S ; 1190 ft./W line	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same as above.	Rio Arriba New Mexico
AT TOTAL DEPTH: Same as above.	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6567 Gr.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	030, 02.
TEST WATER SHUT-OFF [3]	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
MULTIPLE COMPLETE	change on Form 9-330.)
CHANGE ZONES	
ABANDON*	
(other)	2
	<u> </u>
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di 	e all pertinent details, and give pertinent dates,
measured and true vertical depths for all markers and zones pertinen	t to this work.)*
1. Spudded 9-7/8" surface hole at 8:00 a.m. 6	5-14-79.
2. Drilled to T.D. of 230 ft. R.K.B.	
3. Ran 5 joints (207 ft.) of 7-5/8", 20 lb.,	F-25 casing. Landed at
221 ft. R.K.B.	25 Gaszing. Samuel as
ZZZ ZC. N.M.Z.	
4. Cemented with 140 sacks of class "B" cemen	nt w/2% CaCl. Cement
circulated to surface. Plug down at 6:00	and New .
Circulated to Surface. Flug down at 0.00	p.m. 0-14-79.
C Maited as second 10 hours and tested assis	- +- 1000 75
5. Waited on cement 12 hours and tested casin	IG TO 1000 ID.
for 15 minutes. Tested OK.	JUN 2 0 1070
Subsurface Safety Valve: Manu. and Type	(Siet @ - 1979 4
1 00	T'E CON. COM
18. I hereby certify that the foregoing is true and correct	DIST. 2
SIGNED Serveth E. Karly TITLE Produ. Supt.	6-15-79
SIGNED Kenneth F. Poddy TITLE Plodu. Supc.	DATE

JUN 1 8 1979

(This space for Federal or State office use)

__ TITLE _