

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 42-R1424/

5. LEASE DESIGNATION AND SERIAL NO.

Jicarilla 101

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla 101

9. WELL NO.

#8

10. FIELD AND POOL, OR WILDCAT

Blanco Mesa Verde
Blanco Pictured Cliffs11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 12, T26N, R4W

12. COUNTY OR PARISH
Rio Arriba13. STATE
New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☐ GAS ☒ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

Southland Royalty Company

3. ADDRESS OF OPERATOR

P. O. Drawer 570, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1070' FSL & 1840' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7027' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Spud and Casing Report ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

7-12-79

Spudded 12 1/4" surface hole at 11:00 AM, 7-12-79 and drilled to a TD of 232'. Set 5 joints (219.36') of 9 5/8", 36#, H-40 casing at 231.36'. Cemented with 110 sacks of Class "B" with 3% CaCl₂. Cement did not circulate. Cemented down backside of casing with 290 sacks of Class "B". Cement circulated to surface.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE District Production Manager DATE 7-16-79

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE

*See Instructions on Reverse Side

JUL 17 1979

U. S. GEOLOGICAL SURVEY
BIRMINGHAM, ALA.