

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR
Northwest Production Inc.
3. ADDRESS OF OPERATOR
Box 289, Farmington, New Mexico 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1450' S, 1630' W
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☒
☐
☐
☐
☐
☐
☐
☐

5. LEASE
Jicarilla Cont. #120
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla
7. UNIT AGREEMENT NAME


8. FARM OR LEASE NAME
Jicarilla 120 C
9. WELL NO.
#18
10. FIELD OR WILDCAT NAME
South Blanco - Pictured Cliff
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 31, T-26-N, R-4-W
N.M.P.M.
12. COUNTY OR PARISH
Rio Arriba
13. STATE
New Mexico
14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6758' 'GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-4-79 Spudded well. Drilled surface hole. Ran 3 joints 8 5/8", 24#, KE surface casing 120' set at 132'. Cemented w/118 cubic feet cement. Circulated to surface. WOC 12 hours held 600# / 30 minutes.



Subsurface Safety Valve: Manu. and Type _____ Set @ _____

18. I hereby certify that the foregoing is true and correct

SIGNED *A. G. Susco* TITLE Drilling Clerk DATE Sept. 6, 1979

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____

*See Instructions on Reverse Side

WILSON
SERVICE COMPANY

FORM 432-2

TEMPERATURE SURVEY

COMPANY..... El Paso Natural Gas Co.
WELL..... 18..... LEASE..... Jicarilla 120 C
COUNTY..... Rio Arriba..... STATE..... New Mexico
SEC. K 31..... TWP..... 26..... RGE..... 4

APPROX. TOP CEMENT..... 1900'

Survey Begins at..... 1500'..... Ft. Ends at..... 3375'..... Ft.
Approx. Fill-Up..... Max. Temp.....
Log Measured From..... KB..... Run No.....

Casing Size..... Casing Depth..... Diam of Hole..... Depth
2 7/8"..... from..... to..... 3 3/4"..... from..... to.....
..... from..... to..... from..... to.....

Date of Cementing..... Time.....
Date of Survey..... 9/11/79..... Time..... 2:00 AM
Amount of Cement..... As per report.....

Recorded by..... Griffey..... Witnessed by.....

REMARKS OR OTHER DATA

None.

TEMPERATURE IN DEGREES FAHRENHEIT

