UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	Contracts #109
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas (X)	Jicarilla B
1. oil gas X other	9. WELL NO.
2. NAME OF OPERATOR	88 M
Tenneco Oil Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Mesaverde/Basin Dakota
720 S. Colo. Blyd., Denver, CO 80222	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17]
below.) 1685'FWL 1020'FNL	Sec. 15; T26N; R5W 12. COUNTY OR PARISH 13. STATE
AT SURFACE: AT TOP PROD. INTERVAL:	1
AT TOTAL DEPTH:	Rio Arriba New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. AFI NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
(C) ONLY ON ONLY DESCRIPTION	6632 'GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	0002 dit
TEST WATER SHUT-OFF	OFFIN
FRACTURE TREAT	/ KILHIM
SHOOT OR ACIDIZE LA	(NOTE: Report results of multiple combiguous arrole
PULL OR ALTER CASING	change on form
MULTIPLE COMPLETE	(NOTE: Report results of multiple completion of the change on form \$200.23 1980
CHANGE ZONES	
ABANDON* U	A DIST YOUR !
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	illectionally dillied. Bive appartiace locations and
8/6-8/11/80	7400 04 7510 7500 7505 71
Perf'd Dakota (2 JSPF): 7396-7402, 7424-7426	, /48U-84, /518-/53U, /505-/1,
7600-7604. Acidized w/350 gals 15% HCL. Forma	ation broke down @ 2250 PSI.
Moved up to 7500'. Spotted 1250 gals 15% HCL	DOWN CUDING OVER Dakota Add
zones. Frac'd. Dakota w/80,000 gals 30# XL ge	21, 80,000# 20/40 Saliu & 25,000#
10/20 sand. Air: 55 BPM. AIP: 2550 PSI. ISIP	1 1900 PS1, 15 MIN SIF. 1000 PS1.
Pulled up 7 jts or 217'. Opened well to flow	. Overmite Site. 1979 FSI, Site.
1300#.	
	RECEIVED
	SEP 1 7 1080
Subsurface Safety Valve: Manu. and Type	U. S. GEOCH SURVEY FT
18. I hereby certify that the foregoing is true and correct	
SIGNED Asst. Div. Admin. Manager 9/11/80	

SEP 221980

*See Instructions on Reverse Side

(This space for Federal or State office use)

____ DATE _

APPROVED BY _______ CONDITIONS OF APPROVALUE ANY:

_ TITLE _