

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
J. Gregory Merrion

3. ADDRESS OF OPERATOR
P.O. Box 507, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 925' FWL & 1720' FNL
AT TOP PROD. INTERVAL: same
AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF:

(other) Spud, set surface casing ☒

RECEIVED

MAY 8 1980

U. S. GEOLOGICAL SURVEY

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-05-80 Spud 12-1/4" hole at 1 p.m. T.D. @ 351'.

5-06-80 Ran 8 jts., 335.46', 8-5/8", 23#, X-42 casing. Set at 350' K.B. and cemented w/ 250 sx Class B 2% CACL₂. Circulated 40 sx to ground surface. Job complete 10:15 a.m. WOC 12 hrs. Installed BOP. Pressure tested casing to 500 psi for 30 min., held ok.


Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED J. Gregory Merrion TITLE Operator DATE May 6, 1980

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:



ACCEPTED FOR RECORD

MAY 8 1980

*See Instructions on Reverse Side

FARMINGTON DISTRICT
BY Mal Kuchera