| NO OF COP ES RECEIVED   |   | Form C-103  |
|---|---|---|
| DISTRIBUTION  |   | Supersedes Old<br>C-102 and C-103   |
| ANTAFE  | NEW MEXICO OIL CONSERVATION COM   |   |
| ILE   | •   |   |
| J.S.G.S.  |   | 5a. Indicate Type of Lease  |
| AND OFFICE  |   | State Fee XX  |
| PERATOR   |   | 5, State Oil & Gas Lease No.  |
| SPERATOR 1  |   |   |
| SUNDRY NO SUNDRY NO SUNDRY NO SEE THIS FORM FOR PROPOSAL                        | OTICES AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT OR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) | RESERVOIR.  |
|   |   | 7. Unit Agreement Name  |
| OIL GAS X WELL X  | THER-   |   |
| Name of Operator  |   | 8. Farm or Lease Name   |
| J. Gregory Merrion  |   | Federal Com   |
| Address of Operator   |   | 9. Well No.   |
| P. O. Box 507, Farming  | top NM 87401  | 4   |
| Location of Well  | 5013 111 07 102   | 10. Field and Pool, or Wildcat  |
| . =   | o South 9   | 70 Ballard Pic. Cliffs  |
| UNIT LETTER 1 101(  | O FEET FROM THE South LINE AND 97   | FEET FROM THE THE TENTE OF THE |
|   | 2/ 25N  |   |
| THE East LINE, SECTION  | 34 TOWNSHIP 25N RANGE   | OW NMPM.  |
|   | TO DE DE CE   |   |
|   | 15. Elevation (Show whether DF, RT, GR, etc.)   |   |
|   | 6373 G.L.   | Rio Arriba  |
| 6. Check Approved Check INTE  | ropriate Box To Indicate Nature of Notic  | e, Report or Other Data SUBSEQUENT REPORT OF:   |
| No Hoz or mile.   |   |   |
|   | PLUG AND ABANDON REMEDIAL WORK  | ALTERING CASING   |
| PERFORM REMEDIAL WORK   | COMMENCE DRILLI   |   |
| TEMPORARILY ABANDON   | r l   | <u> </u>  |
| PULL OR ALTER CASING  |   |   |
|   | OTHER   |   |
| OTHER   |   |   |
| 7 Describe Proposed or Completed Operati  | ons (Clearly state all pertinent details, and give perti  | nent dates, including estimated date of starting any proposed   |
| work) SEE RULE 1 103.   | , ,   |   |
| Spudded 9-3/4" hole 8-  | 9-80. Drilled to 98'. Ran 98'   | of 7", 20#, J-55 casing. Set  |
| at 98'. Cemented with 60 sax Class B cement with 3% CACL2. Displaced to 70' and |   |   |
| circulated 15 sax to ground surface.  |   |   |
|   |   |   |
| Waited on cement 12 ho  | urs. Installed BOP. Pressure t  | ested casing to 500 psi. Held ok.   |
| waited on comenc 12 mg  |   |   |
|   |   |   |
|   |   |   |
|   |   |   |
|   |   |   |
|   | •   | All had been a second   |
|   |   | 1000  |
|   |   | 1000  |
|   |   | Higgs Com.  |
|   |   |   |
|   |   |   |
|   |   |   |
|   |   |   |
| _   |   |   |
| 100   |   |   |
| 8. I hereby certify that the information above                                  | ve is true and complete to the best of my knowledge an  | d belief.   |
| # 1 L   |   |   |
|   | lmoy Operator   | B-22-80   |
| IGNED   | 1 11166   |   |
| Original Signed by FRANK  | T CHAVE7  | ALIC 9 E 100/   |
| Sugmor signed by rawita   | I. CHAVEZ SUPERVISOR DIS  | TRICT # 3 AUG 25 1980   |

CONDITIONS OF APPROVAL, IF ANY: