

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well ☐ gas ☐ well ☐ other ☒ Drilling

2. NAME OF OPERATOR
Marathon Oil Company

3. ADDRESS OF OPERATOR
P.O. Box 2659 Casper, WY 82602

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1,850' FNL & 1,685' FWL Unit F
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐

(other) Please see below

5. LEASE
Contract 154

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jicarilla Apache

9. WELL NO.
14E

10. FIELD OR WILDCAT NAME
Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 34, T26N, R5W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
New Mexico

14. API NO.
30-039-22591

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6,566' GL, 6,579' KB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PROGRESS REPORT

See Attachments

From: 3-27-82 To: 4-21-82

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED ME. Kuyh TITLE Drilling Superintendent DATE 4-26-82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

NMCCC

MAY 1 1982
FARM/STATE L.S. NOT
BY SMH

JICARILLA APACHE #14E WELL HISTORY

3-27-82/

4-16-82 SI.

4-17-82 SI. SET 1.81" CIRC BLANKING PLUG IN BAKER MODEL "F" NIPPLE @ 5,256' KB (31' ABOVE PKR).

4-18-82/

4-19-82 SI.

4-20-82 MOVED DRAKE WORKOVER UNIT ON LOCATION. RU, BLEW TBG DOWN CIRC BLANKING PLUG, SET IN MODEL "G" NIPPLE 1 JT ABOVE PKR. INSTALLED BOP. PKR SHEARED @ 58,000#. PULLED 1 JT 2-3/8" TBG & 10' SUB. PKR DRAGGING, SANDED OFF PULLING 55,000#. WORKED TBG & PKR W/CSG FLOWING TO CLEAN SAND FROM AROUND PKR SEALS, ETC. PULLED 10 STANDS-PKR SANDED OFF AGAIN. PKR NOW 300' ABOVE POINT LOOKOUT PERF.

4-21-82 TRIED TO WORK PKR LOOSE, WOULD NOT MOVE. PMPD 45 BBLS 2% KCL WTR DOWN CSG WHILE PULLING STRAIN ON TBG & PKR. AFTER 2 HRS, PKR PULLED FREE. PULLED TBG, BLAST JTS & PKR OUT OF HOLE. SUSPECT THAT PKR DID NOT SET PROPERLY OR HAD SOME OBSTRUCTION BETWEEN SEALS & CSG.

