

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E 291 17	E 291 26

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)


1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Caulkins Oil Company		8. Farm or Lease Name State A
3. Address of Operator P.O. Box 780 Farmington, New Mexico		9. Well No. 113 E
4. Location of Well UNIT LETTER <u>P</u> <u>1110</u> FEET FROM THE <u>South</u> LINE AND <u>950</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>26N</u> RANGE <u>6W</u> NMPM.		10. Field and Pool, or Wildcat Otero Chacra, Blanco Mesa Verde, Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 6646' GR		12. County Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>



17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of start of any proposed work) SEE RULE 1103.

Spud at 4:30 PM 6-08-81.

Drilled 13 3/4" hole to 289'.

Ran 9 5/8" 30.30# H-40 casing to 289' and cemented with 250 sacks cement, 2% CaCl.

Cement circulated to surface.

Plug down 11:30 PM 6-08-81.

6-09-81 Tested surface casing with 1200# for 30 minutes. No decrease in pressure.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Vergara TITLE Superintendent DATE 6-10-81

APPROVED BY Original Signed by FRANK I. CHAVEZ TITLE SUPERVISOR DISTRICT # 3 DATE JUN 12 1981

CONDITIONS OF APPROVAL, IF ANY: