

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐  
2. NAME OF OPERATOR  
Caulkins Oil Company  
3. ADDRESS OF OPERATOR  
P.O. Box 780 Farmington, New Mexico  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 920' F/S & 1100' F/E  
AT TOP PROD. INTERVAL: Same  
AT TOTAL DEPTH: Same



16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

☒  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spud at 2:00 PM 7-16-81.  
Drilled 13 3/4" hole to 291'

Ran 9 5/8" 32.7# H-40 casing to 291' and cemented with 250 sacks Class B cement, 2% CaCl.

Plug down 12:00 Midnight 7-16-81.

Cement circulated to surface.

7-18-81 Cement set 24 hours. Tested 9 5/8" casing with 600# for 30 Minutes. No decrease in pressure.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Charles D. Ogden TITLE Superintendent DATE July 20, 1981

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

NMOC

ACCEPTED FOR RECORD

JUL 29 1981

FARMINGTON DISTRICT