Form 9–331 Dec. 1973		Form	1 Approved	j.	
UNITED STATES	F	Budg	et Bureau	No. 42-R1	424
DEPARTMENT OF THE INTERIOR	5. LEASE SF 079	025 4		1 "	
GEOLOGICAL SUPPER TO A	6. IF INDIAN		CO TOU	DE 21445	
		', ALLUITE	LURIKI	SE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to depend or plur back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGI	REEMENT N	AME		
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR	LEASE NAM	AE.		
1. oil gas well other OIL CON. COM.	Breech	A			
2. NAME OF OPERATOR	9. WELL NO	. , 0.	ين د		
Caulkins Oil Company	628E	68			
3. ADDRESS OF OPERATOR	10. FIELD OR		IAME	•	
P.O. Box 780, Farmington: New Mexico	Basin Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OR				
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA	R., M., OR E	ILK. AND	SURVEY	OR
below.) 1980 F/N & 660 F/W	1	10 26N			
AT SURFACE:	12. COUNTY	OR PARISH	13. ST	ATF	
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same		iba			
	14. API NO.		. ALCW	HEALLU	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		· · · · · · · · · · · · · · · · · · ·			
REPORT, OR OTHER DATA	15. ELEVATIO	NS (SHOW	DF, KD	B, AND V	VD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6638 C	r			
TEST WATER SHUT-OFF TEST WATER SHUT-OFF TEST TEST					_
FRACTURE TREAT					
SHOOT OR ACIDIZE				:	
PULL OR ALTER CASING	(NOTE: Report	results of mu	itiple com	pletion or z	one
MULTIPLE COMPLETE	change	e on Form 9-3	330.)		
CHANGE ZONES		•			1
ABANDON*			-		:
out of the same of					•
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent 10-23-81 Drilled to TD 7600*	t to this work.)*	etails, and d, give subs	give per surface le	tinent dat	tes, and
Ran Induction Electric and Gamma R	ay Log.				
Ran New 5½" Casing as follows: 7600' to 6714' 4½" 11.6# J-55 Smls	0 1 .1 1				
6714' to 716' 4½" 10.5# J-55 Smls	ord thd.				
716' to Surface 4½" 11.6 # J-55 Si	ord thd.	1			
Cemented 42 Csg w/ 100 sacks neat	followed to	1. 	1 •		
down 3:00 A.M. 10-24-81. Temperatus	re survey (borro co	acks 1	atex.	Plug
	re survey s	mows cer	nent t	Op @ 3	700
			٠		
		=			
Subsurface Safety Valve: Manu. and Type		Set @	മ		F+
18. I hereby certify that the foregoing is true and correct			3		
				•	
SIGNED Charle CurquentLE Superintendent	DATE 1	2-10-81			

*See Instructions on Reverse Side

EEC 15 1981

FARMINGTON DISTRICT