6 - USGS 1 - File 2 - MF

Dec. 1973				Approved. t Bureau No. 42–R1424	\$
UNITED S		5. LEASE			-
DEPARTMENT OF	NM 28709				
GEOLOGICAL	. SURVEY	6. IF IND	IAN, ALLOTTEE (OR TRIBE NAME	_
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different			7. UNIT AGREEMENT NAME		
reservoir. Use Form 9–331–C for such propos	or to deepen or plug back to a different cals.)		OR LEASE NAME		-
1. oil gas well other		Divi 9. WELL I	ide 🛂	-	_
2. NAME OF OPERATOR		-	NO. 1 7 7 7		
Dugan Production Co	rp		OR WILDCAT NA		-
3. ADDRESS OF OPERATOR			signated M		
P 0 Box 208, Farmin 4. LOCATION OF WELL (REPORT LO	Gton, NM 8740]	11. SEC., T	「., R., M., OR BL	K. AND SURVEY OF	R
below.)	·		<u>35 T</u> 26N R2	w 3	
AT SURFACE: 1570 AT TOP PROD. INTERVAL:	' FNL - 1030' FEL		Y OR PARISH		-
AT TOT PROD. INTERVAL: AT TOTAL DEPTH:			Arriba =	NM	_
16. CHECK APPROPRIATE BOX TO	INDICATE NATURE OF NOTICE	_ 14. API NO). 학교되는 발표하다	B 6412	
REPORT, OR OTHER DATA	MONE NATURE OF NOTICE,	15 FLEYA	FIONS (SHOW I	우 일품글3 DF, KDB, AND WD	_
DEGUEST FOR ASSESSMENT		770		JF, KUB, AND WD)
REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF	TED	# 1 1 se		•
FRACTURE TREAT		41	1 5 € 3 € 0	- 변 조육(33) - 67 (32)2 (3	
SHOOT OR ACIDIZE		1983 (NOTE: Rec			
REPAIR WELL PULL OR ALTER CASING	1 9 N V V V	NOTE: Rep	ort esults of mult	iple completion or zone	e
MULTIPLE COMPLETE		SURVERSUR M.	nge on Form 9-33	0.) 	:
CHANGE ZONES		Con, No.	율췙픿죮		·
ABANDON* (other) Request for Extension	on of Time	<u>.</u>	ମୁଖିଲିଲ		
		3	2		; <
17. DESCRIBE PROPOSED OR COMP	LETED OPERATIONS (Clearly stat	e all pertinen	t details, and g	ive pertinent dates	: i,
including estimated date of starti measured and true vertical depths	for all markers and zones pertined	irectionally dr nt to this work.	illed, give subsu .)*	irface locations and	i
Have been in 17 1				- 출시점(호 <u>함</u>	
nave been unable to	perform work on this we	ell as ind	licated on c	our sundry	
road conditions.	d approved by BLM 2-22	-83, aue t	o weather a	ind - 15	
roud conditions.			Fig. 15		
Request 15 additiona	I days to conduct this	work.	W-6		•
•	11 days to conduct this Extended to 5-2	7-87			3
	LX/MING /4 3 = 2		三重节严重 靜		
			A 3 8		
			ا 😅 🕻 🕻		ı
	·			Line C	•
Subsurface Safety Valve: Manu. and Ty	pe		Set @	Ft.	
18. I hereby certify that the foregoing is					
SIGNED Jim L. Jacobs	Geologist Geologist	DATE _	4-21-83		_
	(This space for Federal or State off	ice use)		APPROVE	5
APPROVED BY			Δ	S-AMENDI	E
CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE		Zoux at	ill
			. /	- MAV A 9 100	∤વ

DISTRICT ENGINEER