
Form 9–331	Form Approved.  Budget Bureau No. 42-R1424	
Dec. 1973 UNITED STATES	5. LEASE	
DEPARTMENT OF THE INTERIOR	USA SF-080658	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) $ \frac{1}{2} \frac{1}$	8. FARM OR LEASE NAME	
1. oil gas well other	Romero Com	
Well Well Outer	9. WELL NO. 1	
2. NAME OF OPERATOR Tenneco 0il Company	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Und. Mesaverde/Chacra	
Box 3249, Englewood, CO 80155	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA	
below.) AT SURFACE: 1,120' FSL, 790' FEL	Sec. 25, T26N, R6W  12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL:	Rio Arriba NM	
AT TOTAL DEPTH:	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6568 GR	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	0000 div	
FRACTURE TREAT		
SHOOT OR ACIDIZE		
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9-330.)	
MULTIPLE COMPLETE		
CHANGE ZONES	i.	
ABANDON*		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined	firectionally drilled, give subsurface locations and	
Per your request; attached is a copy of the	temperature survey which	
determined the top of the cement behind the	SEP 23 1982 DIST. 3	
Subsurface Safety Valve: Manu. and Type	Ft	
18. I hereby centify that the foregoing is true and correct	,	
SIGNED ACCURATE Production An	alyst <sub>DATE</sub> September 9, 1982	
(This space for Federal or State of		
APPROVED BY	DATE DECORIO	

ACCEPIED FOR RECORD

SEP 2 1 1982

\*See Instructions on Reverse Side

NMOCC.



## WILSON

## SERVICE COMPANY

## TEMPERATURE SURVEY

COMPANY	Tenr	eco Orl Co.	**************************************	e - Majore e e e e e e e e e e e e e e e e e e
WELL #1		LEASE	Ro	mero Con.
COUNTY	Rio Arriba	STATE	New Mex	
SEC. 25	TWP.	36N	RG	610
APPROX. TOP	CEMENT	800	The strict Miller was the fine that a surface work to the	
Survey Begins at				
Approx. Fill-Up				
Log Measured From	KB	Run No.	* (\$0.11.12.12.0.0.0.13	e Blance and Company
Casing Size				
K .				
from	to		rom	<b>to</b>
from	to	<u>.</u>	rom	to
from	to		rom	to
from	to 8/5/3	6.2	rom Tirne	to
from  Date of Cementing	8/5/3		Time	to
from  Date of Cementing  Date of Survey  Amount of Cement	8/5/3	B.C B.L Lydix - h. Luv	rom Time Time	to
from  Date of Cementing  Date of Survey  Amount of Cement	8/3/3 8/3/3 205 Sks tol Mahaffey REMARKS OF	Witnessed b	Time Time	to

TEMPERATURE IN DEGREES FAHRENHEIT

300 400 500 t 600' 700 ° 8001 Anomoly 800' 9001 1000' 1100' 1200'

1300'