

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
Burns Fee	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name <u>East</u>
2. Name of Operator <u>Benson-Montin-Greer Drilling Corp.</u>		8. Farm or Lease Name <u>East</u>
3. Address of Operator <u>221 Petroleum Center Building, Farmington, NM 87401</u>		9. Well No. <u>35 (M-9)</u>
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>south</u> LINE AND <u>660</u> FEET FROM THE <u>west</u> LINE, SECTION <u>9</u> TOWNSHIP <u>26N</u> RANGE <u>1E</u> NMPM.		10. Field and Pool, or Wildcat <u>Puerto Chiquito Mancos, East</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>7102' GL</u>		12. County <u>Rio Arriba</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER Production casing cementing ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/19/83 Ran production casing string consisting of 84 joints
3312.16' TO--3330.64' overall 4-1/2" 11.6# N-80 8-round
Range 3 LT&C casing set at 3308'. Cement with 142 cubic
feet cement slurry (Class B regular cement) with 1/4#
celoflake per sack.

Equipment used: 4-1/2" Texas pattern shoe
float collar
6 centralizers
1 stop ring

7/20/83 Cement top by Wilson Service Company temperature survey
800' below surface.

Pressure tested 4-1/2" production casing to 1500# held
for 30 minutes with no pressure drop.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Vice-President DATE July 30, 1983

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DATE AUG 24 1983

CONDITIONS OF APPROVAL, IF ANY: