APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

5. LEASE

Contract 118

UNITED STATES DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Jicarilla 118 A	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)		
1. oil gas other other 2. NAME OF OPERATOR	9. WELL NO. #1	
Robert L. Bayless 3. ADDRESS OF OPERATOR P.O. Box 1541, Farmington, NM 87499	10. FIELD OR WILDCAT NAME Sleeper Pic. Cliffs 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1130' FNL & 1130' FEL AT TOP PROD. INTERVAL: same AT TOTAL DEPTH: same	Sec. 26, T26N, R3W 12. COUNTY OR PARISH 13. STATE New Mexico 14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7390 CL	
SHOOT OR ACIDIZE	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and	
See Attached Sheet.		
Subsurface Safety Valve: Manu. and Type	Set @ Ft.	
18. I hereby certify that the foregoing is true and correct		

_____ DATE ____ _ TITLE _

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

OCT 26 1983



- 10-17-83 Move in, rig up Bayless Rig 4. Rig up to pull rods. Pulled 155 5/8" rods. Rod body break in rod 156 @ 3875 ft. (rod just above pump). SDFN.
- 10-18-83 Fished remaining rod and pump. Replaced 7 scrapered 5/8" rods, 3 plain 5/8" rods, and broken 5/8" rod with new plain 5/8" rods. Replaced $1\frac{1}{2}$ " pump with 1-1/16" pump. Landed as follows:

DESCRIPTION	LENGTH	DEPTH
KB to landing point Polished rod 1½" X 16' with 5/8" rod subs 97 5/8" scrapered rods 59 5/8" regular rods Pump 2" X 1-1/16" X 16' (bottom hold down)	10.00 1½" liner 16.00 6.00 2425.00 1475.00 16.00 3948.00	0-10 10-26 26-32 32-2457 2457-3932 3932-3948

Started pumping unit. Released rig.