## TABULATION OF DEVIATION TESTS

## AMOCO PRODUCTION COMPANY

DEPTH	DEVIATION	
DEPTH  188' 347' 837' 1087' 1362' 1581' 1896' 2134' 2633' 3134' 3448' 3760' 4042' 4200' 4452' 4764' 5323' 5597' 6036' 6665' 6913' 7408' 7908'	3/4° 1/4° 1-1/2° 1-1/4° 1-1/2° 1-1/2° 1-1/2° 1-3/4° 1° 1-1/4° 1-3/4° 2-1/4° 2-1/4° 1-3/4° 2° 2° 2° 2-3/4° 3-1/4° 3-1/4° 1/2° 1-1/2°	RECEIVED
8138'		OIL CON. DIV.

## <u>A F F I D A V I T</u>

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation tests taken on AMOCO PRODUCTION COMPANY'S

Jicarilla Apache A 118 No. 24, SE/NE Section 25, T26N, R3W, Rio Arriba County, New Mexico.
Signed Signed
Title Adm. Supervisor
THE STATE OF NEW MEXICO)  SS.
COUNTY OF SAN JUAN ) SS.
BEFORE ME, the undersigned authority, on this day personally appeared  B. D. Shaw known to me to be Adm. Supervisor  for Amoco Production Company and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.
SUBSCRIBED AND SWORN to before me, a Notary Public in and for said County and State this 16th day of July , 1987.  Notary Public

My Commission Expires: June 16, 1989