			5. Lease		
UNITED STATES			NMNM-03554		
DEPARTMENT OF THE INTERIOR			,	((((((((((((((((((((((((((((((((((((((	
BUREAU OF LAND MANAGEMENT					
OUNDRY NOTIONS AND DEPONING OFFICE A			6. If Indian, Allottee or Tribe Name		
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.			7. Unit Agreement N	ame	
Use "APPLICATION FOR PERMIT" for such proposals)					
	as Well [] Other []		8. Well Name and No	).	
			BREECH "C" 144-E		
2. Name of Operator:			9. API Well No.		
Caulkins Oil Company			30-039-24386		
3. Address of Operator: (505) 632-1544			10. Field and Pool, Exploratory Area		
P.O. Box 340, Bloomfield, NM 87413  4. Location of Well (Footage, Sec., Twp., Rge.)			Blanco Mesa Verde		
4. Location of Well (Footage, Sec., Twp., Rge.)  190 FNL2 1650 FWL Sec. 12 - 2614 - 6W			11. Country or Parish, State		
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NO			Rio Arriba Co., New Mexico		
	OF SUBMISSION	TYPE OF ACTION	DITCE, REPOR	1, OR OTHER DATA	
<del></del>				I I Cl CDI	
[ ] Notice of Intent		[ ] Abandonment [X]Recompletion		[ ] Change of Plans [ ] New Construction	
[X] Subsequent Report		[ ] Plugging Back		Non-Routine Fracturing	
•	•	Casing Repair		Water Shut-Off	
[] Final Aband	donment Notice	[ ] Altering Casing		[ ] Conversion to Injection	
	<del>,</del> -, . ,	[ ] Other		[ ] Dispose Water	
	or Completed Operations:				
10-6-97	Rigged up.				
	Pulled 2 3/8" Tocito produc	etion tubing.	_		
	Released seal assembly from model "D" packer at 6944'.			)ECENTA	
	Pulled 1 1/2" Dakota produ	ection tubing with seal assembly.	IJl	PECETYED DEC - 8 1897 D	
10-7-97	Set 7" retrievable bridge pl	ug at 6926' to temporarily abandon Da	akota zone.		
	_	tool did not shear from top of plug.		DIST. 3	
	Set 2 <sup>nd</sup> 7" retrievable bridg	e plug at 5900' to temporarily abandon	Tocito zone:		
10-8-97	Perforated Mesa Verde zone with thirty holes from 4911' to 5816'.				
	Fractured Mesa Verde with	3076 bbls slick water and 140,128# s	and.		
NOTE: The for	Continued on page 2.	S. BLM Form 3160-5			
18. I HEREBY (	CERTIFY THE FOREGOIN	G IS TRUE AND CORRECT			
SIGNED: Robert Z Zangare TITLE: Superintendent DATE: November 24 1997 DEADER					
ROBERT L. VERQUER  TITLE: Superintendent DATE: November 24, 1997 RECORD					
APPROVED BY: TITLE: DATE: DEC 0.1 1997					
CONDITIONS OF APPROVAL, IF ANY					
<del></del>			FARMIN	GTON DISTRICT OFFICE	
			21		

Caulkins Oil Company Sundry Notice for Breech "C" 144-E November 24, 1997 Page 2

10-22-97 thru 10-31-97	Fished for retrievable bridge plug at 5900' and setting tool with collar locator from top of bridge plug at 6926'.			
	Pulled bridge plug from 5900'.			
	Recovered setting tool from top of pridge plug at 6926'.			
	Ran 7" model "C" retrievable bridge plug and set at 5879'.			
	Dakota temporarily abandoned with retrievable bridge plug set at 6926'.			
	Tocito temporarily abandoned with retrievable bridge plug set at 5879'.			
11-1-97	2 3/8" Mesa Verde production tubing landed on donut at 5818'.			
11-11-97	Ran 3 hour potential test – calculated volume at 1719 MCF/D.			
	Well now shut-in waiting on NMOCD C-104 approval to produce.			