

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. SF-080436-B	
2. NAME OF OPERATOR Benson-Montin-Greer Drilling Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 221 Petroleum Center Bldg., Farmington, NM 87401		7. UNIT AGREEMENT NAME Canada Ojitos Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface SE NE 1632' FNL, 1139' FEL, Sec. 8, T26N, R1W		8. FARM OR LEASE NAME	
14. PERMIT NO.		9. WELL NO. 43 (H-8)	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7785' GR		10. FIELD AND POOL, OR WILDCAT W. Puerto Chiquito Mancos	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 8, T26N, R1W	
		12. COUNTY OR PARISH Rio Arriba	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input checked="" type="checkbox"/>	Ran & cement 5 1/2" liner	<input checked="" type="checkbox"/>
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

09/10/89 Ran 1465.7' of 5 1/2" 23# N-80 casing plus cement guide shoe, float collar, landing collar and liner hanger, total liner length 1478.52'. Ran to 8450'.

Cemented with 435 sacks (500 cu. ft.) Class G cement. Displaced 83.7 barrels.

L, 7061 - 8450

RECEIVED
OCT 06 1989
OIL CON. DIV
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Virgil L. Stoabs TITLE Vice President DATE 09/26/89
(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side