Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	FORM APPROVED
	Budget Bureau No. 1004-0135 Expires: March 31, 1993
	Expires March 31, 1993
5.	Lease Designation and Serial No.

NOTICES AND REPOR posals to drill or to deep CATION FOR PERMIT — SUBMIT IN TRIP	pen or reentry to a different reservol - " for such proposals	NM 046 6. If Indian Allottee or Tribe Name 7. If Unit or CA Agreement Designation
posals to drill or to deep CATION FOR PERMIT -	pen or reentry to a different reservol - " for such proposals	7. If Unit or CAL agreement Designation
CATION FOR PERMIT -	- " for such proposals	7. If Unit or CA Agreement Designation
		1
0000000		1 2 •
	207 20 20	
	Thursday.	Cheney Federal B 2
ORATION	MAY 20 W	9. API Well No.
	[30-039-25266
,	4,174	10. Field and Pool, or exploratory Area
R., M., or Survey Description)		Blanco MV
ec. 8, T26N, R2W, N.	M.P.M.	11. County or Parish, State
,	A CONTRACTOR OF THE SECOND SEC	Rio Arriba NM
	THE OF MOTION DE	
RIATE BOX(s) TO IN	IDICATE NATURE OF NOTICE, RE	TOTT, ON OTHER BATTA
	TYPE OF A	ACTION
	Abandonment	Change of Plans
	Recompletion	New Construction
	X Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
t Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water (Note: Report results of multiple completion on We
		Completion or Recompletion Report and Log form.
ing. Stuck. Cut tublications at 54 tretainer set at 54 lass B cement. (821 282-4924 with 35 holomout with air mist.	cu. ft.) Capped retainer with 1 les. TIH with packer set at 4190 am and 134,000# 20/40 sand. Flow	0'. Acidized with 1000 gals 15% w back to pit.
g is true and correct	Title Production Assistant	Date 5/15/00 5-24-00
	PRATION Y. Farmington, NM 8 R., M., or Survey Description) eC. 8, T26N, R2W, N. RIATE BOX(s) TO IN An in a survey and the second sec	PRATION Y. Farmington. NM 87401 R., M., or Survey Description) ec. 8, T26N, R2W, N.M.P.M. RIATE BOX(s) TO INDICATE NATURE OF NOTICE, RE N TYPE OF A Abandonment Recompletion X Plugging Back Casing Repair Altering Casing Other ations (Clearly state all pertinent details, and give pertinent dates, including estimated or measured and true vertical depths for all markers and zones pertinent to this work.)* lay down rods. ing. Stuck. Cut tubing at 6958'. TOH. t retainer set at 5401'. Squeeze cement Mancos with lass B cement. (821 cu. ft.) Capped retainer with 1 282-4924 with 35 holes. TIH with packer set at 4190 out with air mist. out to 5200'. Jet hole clean. TOH. 3/8" 4.7# J-55 tubing set at 4911'. Installed well