Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budger Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No. SF 079302-B

	-	• , .		_		
~	If I	Mian	Allorte	e or	Tribe	Nam

this form for proposals to dr	AND REPORTS ON WELLS ill or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT	7. If Unit or CA, Agreement Designation	
		RINCON UNIT
1. Type of Well Oil Gas Well Well Other	8. Well Name and No.	
Weil Weil Other 2. Name of Operator	RINCON UNIT #11E	
UNION OIL COMPANY OF CALIFORNI	30-039-25486	
3. Address and Telephone No.	10. Field and Pool, or Exploratory Area	
P.O. Box 2620, Casper, WY 8260 Location of Well (Footage, Sec., T., R., M., or Survey D	Basin Dak/S.Blanco	
	11. County or Parish, State TOCITC	
2080' FSL & 2410' FEL	Rio Arriba, N.M.	
Sec. 6, T26N-R6W	THE OF NOTICE REPOR	OR OTHER DATA
	s) TO INDICATE NATURE OF NOTICE, REPOR	
TYPE OF SUBMISSION	TIPE OF ACTION	Channel Plant
Notice of Intent	Abandonment	Change of Plans New Construction
FF.	Recompletion Plugging Back	Non-Routine Fracturing
X Subsequent Report	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing Other WEEKLY DRILLING REPORT	Conversion to Injection Dispose Water
_	il pertinent details, and give pertinent dates, including estimated date of starting cal depths for all markers and zones pertinent to this work.)*	Completion or Recompletion Report and Log Ic
(SEE ATTACHED WEEKLY DRILLI	NG REPORT)	
14 I hereby certify that the foregoing is true and correct Signed	Title Drilling Superintendent ACCEPTED	Date Date Date DECORD
tle :8 U.S.C. Section 1001, makes it a crime for any person	on knowingly and willfully to make to any department or agency of the United	Stanson 1995 fictitious or fraudulent stal

RINCON UNIT #11E RIO ARRIBA CO., N.M.

WEEKLY SUMMARY

- Moved in Drake # 19 Pulling Unit. Changed out tubing head for dual completion. Rigged up unit. Nippled up BOP and tested casing against blind rams to 3000 psi and holding OK. P/U 6 1/8" bit,6 x 3 1/8" D.C. and TIH to 628' SW-SDON Held safety meeting and inspected rig.
- 6-30-95
 Continued TIH w/6 1/8"bit and tagged at 5046'. Pressure tested casing to 3000 psi and held OK. Drilled down to DV 5051'and drilled thru DV.
 Drilled on DV for 3.5 Hrs. Pressure tested casing to 3000 psi and held OK.
 Continued TIH to 7362'and wash to 7420'. Pressure tested casing to 3000 psi and held OK. TOH to 7360' SW-SDON
- TIH to 7415' (5'above F.Collar). Load hole W/292 BBL 2% KCL.

 TOH w/6 1/8" Bit and 6x DC. Rigged up Sch-J. Tagged F.Collar 7411' WIM

 Logged CCL-GR-CBL 7411'-6700' w/0 casing pressure, log shows good to fair
 bond.Logged CCL-GR-CBL 7411'-4600' w/1000 psi on casing pressure, log shows
 Good bond across Dakota, Tocito and Graneros. Perforated Dakota w/ Sch-J 4"

 HEGS guns, SPF 90 deg. phase, 23 gram charge. 45" holes. Correlated w/ Sch-J
 Phasor Induction log May 18,1995.

 Dakota Perforations
 7290'-7303' 13' 26 Holes
 7360'-7394' 34' 68 Holes
 63' 126 Holes

63' 126 Holes

Note: No change in fluid level after perforating. Checked guns and all fired Rigged down Sch-J.TIH w/notehed collar to 7315' SW-SDON

Cost \$16523 for 7458" (254 jts) 23/8" 4.7# J-55 EUE Tubing

- 7-2-95 Standby to spot 7 1/2% HCL across Dakota perforations today 7/2/95 and Frac. 7/3/95.
- 7-3-95

 TIH to 7406'w/ open ended 2 3/8" tubing Rigged up Dowell and tested lines to 1000 psi. Spotted acid from 7406'- 7103' 500 gal.(12 bbl)7 1/2% HCL w/ 2 gal A260 inhibitor.5gal. F75N surfactant and 5# gal.158 Tron gent Pumped 21/2 RPM 450 psi.Rigged down Dowell Spotted acid 2:00pm 7/3/95 TOH W/ 2 3/8" tubing. Prep. for isolation tool SW-SDON Dakota Perforations 7290'-7303' 13' 7356'-7352 16' 7360'-7394' 34'

Held safety meeting before starting to spotting acid. Dowell on location rigging for Frac.