Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

6. If Indian, Allottee or Tribe Name

SF 079160

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to dr Use "APPLICATION FO	ill or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA. Agreement Designation RINCON UNIT
1. Type of Weil Oil Weil Weil Other 2. Name of Operator UNION OIL COMPANY OF CALIFORNIA 3. Address and Telephone No. P. O. Pow 2620 Casper. WY 82602 (307) 234-1563		8. Weil Name and No. RINCON UNIT #304 9. API Weil No. 30-039-25487 10. Field and Pool, or Exploratory Area
P.O. Box 2620, Casper, WY 82602 (307) 234-1563 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1850' FNL & 1480' FEL (SW NE) Sec. 11, T26N-R7W 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPOR		Basin Dak/Blanco M.V II. County or Parish. State Rio Arriba, NM BT OR OTHER DATA
	s) TO INDICATE NATURE OF NOTICE, REFO	THI, OH OTHER DAME
TYPE OF SUBMISSION Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other WEEKLY DRILLING REPOR	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection
give subsurface locations and measured and true vertical states of the subsurface sociation and measured and true vertical states of the subsurface locations and measured and true vertical states of the subsurface locations and measured and true vertical states of the subsurface locations and measured and true vertical states of the subsurface locations and measured and true vertical states of the subsurface locations and measured and true vertical states of the subsurface locations and measured and true vertical states of the subsurface locations and measured and true vertical states of the subsurface locations and measured and true vertical states of the subsurface locations and measured and true vertical states of the subsurface locations and true vertical stat	AUG 1 7 1000 ONL COMO DIEC. 3	RECEIVED BLM 95 AUG 11 FN 1:34
14. I hereby certify that the foregoing is true and correct Signed Tim Sensor (This space for Federal or State office use) Approved by Conditions of approval, if any:	Title Drilling Superintendent Title ACCEPT	Date 8-7-95 Date ED FOR RECORD
	n knowingly and willfully to make to any department or agency of the Unfath	1624 5 1995 CONGRES OF TRANSMICTOR STATE

*See instruction on Reverse Side

NMOCD

FARMINGTON DISTRICT OFFICE
BY

RINCON UNIT #304 RIO ARRIBA CO., N.M.

WEEKLY SUMMARY

8-1-95

SITP 300,SICP 925 psi per 12 hrs.Flared off gas to pit. Ran and landed 165 jts(5147.18')2 3/8" 4.7# J-55 EUE 8rd tbg at(5161.18')w/ top of seat nipple at (5129')N/D BOP. N/U dual completion tree.Test tree seals to 3000 psi.Pumped 4 bbls 2% KCL water down Dakota tbg and pressured up w/ air to 1200 psi to release pump out plug.Rig down pulling unit and equip.Release well to production dept at 12:00 pm, 7/31/95.

3.3.164.