

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

COPY

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

RECEIVED
BLM

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals. 98 FEB 17 AM 6:46 JERQUE, N.M.		5. LEASE DESIGNATION AND SERIAL NO. CONT. 104																				
SUBMIT IN TRIPLICATE		6. IF INDIAN, ALLOTTEE OR TRIBE NAME JICARILLA																				
1. TYPE OF WELL OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR CONOCO INC.	7. IF UNIT OR CA, AGREEMENT DESIGNATION JICARILLA E																				
3. ADDRESS AND TELEPHONE NO. 10 Desta Drive, Ste. 100W Midland, Texas 79705-4500 (915-686-5424)	4. LOCATION OF WELL (Footage, Sec., T., R., M., or Survey Description) 1190' FNL & 1845' FWL, UNIT LETTER "C", SEC 16, T-26-N, R-04-W	8. WELL NAME AND NO. 15E																				
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		9. API WELL NO. 30-039-25736																				
<table border="1"><thead><tr><th>TYPE OF SUBMISSION</th><th>TYPE OF ACTION</th></tr></thead><tbody><tr><td><input type="checkbox"/> Notice of Intent</td><td><input type="checkbox"/> Abandonment</td><td><input type="checkbox"/> Change of Plans</td></tr><tr><td><input checked="" type="checkbox"/> Subsequent Report</td><td><input type="checkbox"/> Recompletion</td><td><input checked="" type="checkbox"/> New Construction</td></tr><tr><td><input type="checkbox"/> Final Abandonment Notice</td><td><input type="checkbox"/> Plugging Back</td><td><input type="checkbox"/> Non-Routine Fracturing</td></tr><tr><td></td><td><input type="checkbox"/> Casing Repair</td><td><input type="checkbox"/> Water Shut-Off</td></tr><tr><td></td><td><input type="checkbox"/> Altering Casing</td><td><input type="checkbox"/> Conversion to Injection</td></tr><tr><td></td><td><input checked="" type="checkbox"/> Other: <u>Spud & casing report - 9-5/8"</u></td><td><input type="checkbox"/> Dispose Water</td></tr></tbody></table> <small>(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)</small>		TYPE OF SUBMISSION	TYPE OF ACTION	<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans	<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input checked="" type="checkbox"/> New Construction	<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing		<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off		<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection		<input checked="" type="checkbox"/> Other: <u>Spud & casing report - 9-5/8"</u>	<input type="checkbox"/> Dispose Water	10. FIELD AND POOL, OR EXPLORATORY AREA BLANCO MV/BASIN DAKOTA
TYPE OF SUBMISSION	TYPE OF ACTION																					
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans																				
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input checked="" type="checkbox"/> New Construction																				
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing																				
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off																				
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection																				
	<input checked="" type="checkbox"/> Other: <u>Spud & casing report - 9-5/8"</u>	<input type="checkbox"/> Dispose Water																				
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) 02/04/98 Spudded well. 02/05/98 Drilled surface hole. Ran 7 joint 9-5/8", 36#, 8RD ST & C, K-55 casing. Total footage 312', depth of shoe 313', depth of collar 266'. Cement with 170 sks. Class B cement w/ 3% CaCl2 and .25#/sk Cello Flake. Displaced 22.1 bbls of H2O. Muddy and cement returns 03 bbls. Bumped plug @ 08:53 a.m. on 02/05/98 w/ 300 psi.		11. COUNTY OR PARISH, STATE RIO ARRIBA, NM																				
14. I hereby certify that the foregoing is true and correct																						
SIGNED <u>Sylvia Johnson</u> (This space for Federal or State office use)		TITLE <u>SYLVIA JOHNSON, As Agent for Conoco Inc.</u> DATE <u>02/12/98</u>																				
APPROVED BY <u>Patricia M. Hester</u> Conditions of approval, if any:		TITLE <u>Lands and Mineral Resources</u> DATE <u>3/5/98</u>																				
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.																						

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

rec'd 2/19/98
COPY

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals	5. LEASE DESIGNATION AND SERIAL NO. CONT. 104
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME JICARILLA
SUBMIT IN TRIPLICATE	
1. TYPE OF WELL OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. IF UNIT OR CA, AGREEMENT DESIGNATION JICARILLA E
2. NAME OF OPERATOR CONOCO INC.	8. WELL NAME AND NO. 15E
3. ADDRESS AND TELEPHONE NO. 10 Desta Drive, Ste. 100W Midland, Texas 79705-4500 (915-686-5424)	9. API WELL NO. 30-039-25736
4. LOCATION OF WELL (Footage, Sec., T., R., M., or Survey Description) 1190' FNL & 1845' FWL, UNIT LETTER "C", SEC 16, T-26-N, R-04-W	10. FIELD AND POOL, OR EXPLORATORY AREA BLANCO MV/BASIN DAKOTA
	11. COUNTY OR PARISH, STATE RIO ARRIBA, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input checked="" type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other: <u>Spud & casing report - 7"</u>	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

02/12/98 Stage 1: Ran 98 joints 7", 23# M-95, LT & C, 8RD casing, total footage @ 3937'. Depth of shoe 3937', depth of collar 3892', stage stool 2823'. Cement w/ 19 sks of 35/65 B POZ, 2% CaCl₂, .25 PPS Cello-Seal, 625 PPS Gilsonite, 51 sks 35/65 B POZ w/8% Gel, 2% CaCl₂, .25 PPS Gilsonite, .25 PPS. Followed by 100 sx of Class B, 2% CaCl₂, .25 PPS Cello Flake. Displaced with 50 bbls of H₂O, 104.2 bbls mud returns. Floats held. Bumped plug @ 20:30 a.m. on 02/12/98 w/ 1250 PSI. Had full returns throughout job.

02/12/98 Stage 2: 7", stage collar depth 2823', stage tool manufacturer is Weatherford. Cement with 340 sks of 65/95 B POZ, 8% Gel, 2% CaCl₂, .25PPS Cello Flake, 6.25 PPS Gilsonite. Followed by 50 sks of Class B, 2% CaCl₂, .25 PPS Cello Flake. Displaced with 111.3 bbls of water w/ muddy returns. Cement returns 11 bbls, 29 sx. Stage stool held. Bumped plug @ 01:30 am on 02/13/98 w/ 2100 PSI. Had full returns throughout job, circ 11 bbls cmt res. pit.

RECEIVED
MAR - 9 1998

14. I hereby certify that the foregoing is true and correct

OIL CON. DIV.
DIST. 3

SIGNED Sylvia Johnson TITLE SYLVIA JOHNSON, As Agent for Conoco Inc. DATE 02/14/98

(This space for Federal or State office use)

APPROVED BY Patricia M Hest TITLE Lands and Mineral Resources DATE 3/5/98
Conditions of approval, if any: