



(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R368.4.
Approval expires 12-31-60.

Santa Fe

Land Office _____
Lease No. 078987
Unit Canyon Largo Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 16, 1959

Well No. 80 is located 1090 ft. from ~~XX~~ N line and 1650 ft. from ~~XX~~ E line of sec. 35
 RE Sec. 35 25N N.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
 Largo Canyon P.C. Ext. Rio Arriba New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6828 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud date 2-16-59.

On 2-17-59. Total Depth 136'.

Ran 4 joints 8 5/8", 32#, J-55 casing (122') set at 132' with 50 sacks regular cement, 2# Gel, 25 cu. ft. Stratocrete "6" & 3# CaCl, circulated to surface.

Held 500# for 30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

El Paso Natural Gas Company

Company _____
Box 997

Address _____
Farmington, New Mexico

By ORIGINAL SIGNED J.J. TILLERSON
Petroleum Engineer
Title _____